

## Approved For Release 2000/06/26: CIA-RDP89B00569R000800030033-8

25X1A 7573 (IN 51181)

TOPSECRET

PAGE TWO

7. READABLE

A SHUTTER MISLATCH OCCURRED AND INVOLVES FRAMES 093 AND 094. METERING SLIGHTLY ERRATIC THRU-OUT, NO OVERLAPS NOTED. GHOSTING OF THE ADJACENT POSITION INDICATOR LAMPS IS NOTICALBE WHILE THE CORRECT POSITION LAMP IS EXPOSED. VERTICAL INDICATOR DOT IS SLIGHTLY OVEREXPOSED AND BLOSSOMED. PRESSURE ROLLER STATIC (CHATTER) IS NOTED ALONG THE INBOARD EDGE OF BUTH 9L AND 9R FILM AND O'VLY SLIGHTLY ALONG THE OUTBOARD EDGE OF THE 9R SIDE. INTERMITTANT SMALL FOR PATCHES OCCUR ALONG THE OUTBOARD EDGE OF THE 9L FORMAT AREA. PATCHES ARE MINOR, POSSIBLY A FORMAT FRAME REFLECTION, AND APPROX. 1.5 INCHES IN DIAMETER. A SCRATCH IS NOTED ON FRAMES 2381 THRU THE MIDDLE OF 3716. THIS SCRATCH BEGINS AT AN EMULSION LIFT ON FRAME 2381. THERE IS A QUALITY DROP OFF TOWARD ALL OUTBOARD CORNERS. SEVERAL OF ABOVE COMMENTS WERE ALSO MENTIONED IN REF. PARA C. APPROX. CLOUD COVER 25 PERCENT.

25X1A

HELD AT FOR REPRODUCTION PURPOSES.

-END OF MSG-